






















DEFINITION OF FEATURES

	POINT	1 POINT / NO ORDER	
	LINE	2 POINTS / NO ORDER	
	PLANE	3 POINTS / NO ORDER	
	ARC	3 POINTS / IN ORDER	
	CIRCLE	3 POINTS / NO ORDER	
	GAP	3 POINTS / NO ORDER	
	ANGLE	4 POINTS / IN ORDER	
	ELIPSE	5 POINTS / NO ORDER	
	RECTANGLE	5 POINTS / NO ORDER	
	SLOT	5 POINTS / NO ORDER	


MULTI-INPUT TOOL *Allows operator to increase the number of points to increase accuracy of measurements.*
Note: Tool will stay "ON" until re-clicked to cancel it.